.

FILE ACT/015/025 FOLDER #7

SCOTT M. MATHESON
Governor

GORDON E. HARMSTON

Executive Director,

NATURAL RESOURCES

CLEON B. FEIGHT
Director



STATE OF UTAH

DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL, GAS, AND MINING 1588 West North Temple Salt Lake City, Utah 84116 (801) 533-5771 OIL, GAS, AND MINING BOARD

CHARLES R. HENDERSON
Chairman

JOHN L. BELL
C. RAY JUVELIN
THADIS W. BOX
MAXILIAN A. FARBMAN
EDWARD T. BECK
E. STEELE McINTYRE

Vacation or Termination of Notice or Order

To the Following Permitee or Operator:		
Name Co-op MINING Co.	- BEAR CANYON MINE	
Mailing Address P.O. Box 1245	HUUTINGTON, UT	·
State Permit No. <u>ACT/015/025</u>	•	
Utah Coal Mining and Reclamation Act, Sectio	n 40-10-1 et. seq., Utah Code Annotated (1953)	:
Notice of Violation No. N 84-4-13	3-3 dated <i>Oc</i>	r. 24 , 19 <i>8</i> 4 .
Cessation Order No. C	dated	, 19
Violation No is hereby	_X_ Terminated _ EFFECTIVE	Vacated because:
Violation No is hereby	X Terminated	Vacated because:
Violation No. 3 is hereby 15	Terminated 24/84	Vacated because:
Date of Service Nov. \$, 1984	Signature of Autrorize	d Representative
Time of Service or Mailing 1:25a.		#4
	Trainic and	

FILE ACT/015/025



SCOTT M. MATHESON Governor

GORDON E. HARMSTON
Executive Director,
NATURAL RESOURCES

CLEON B. FEIGHT
Director

STATE OF UTAH

DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL, GAS, AND MINING 1588 West North Temple Salt Lake City, Utah 84116 (801) 533-5771 OIL, GAS, AND MINING BOARD

CHARLES R. HENDERSON
Chairman

JOHN L. BELL
C. RAY JUVELIN
THADIS W. BOX
MAXILIAN A. FARBMAN
EDWARD T. BECK
E. STEELE McINTYRE

Modification of Notice or Order

To the Following Permitee or Operator:
Name CO-OP MINING CO BEAR CANYON MINE
Mailing Address P.O. Box 1245 HUDTINGTON, UT
State Permit No. ACT/015/025
Utah Coal Mining and Reclamation Act, Section 40-10-1 et. seq., Utah Code Annotated (1953):
Notice of Violation No. N 84-4-13-3 dated
Cessation Order No. C
Violation No is modified as follows: BOTH VIOLATIONS ARE EXPENDED TO NOV. 15, 19 TO ALLOW TIME TO COMPLETE REMEDIAL ACTION
The reason for this modification are as follows: WHICH HAVE BEEN INITIATED.
Violation No is modified as follows: INCONSTRUCTION IS BASED UPON FIELD
The reasons for this modification are as follows: INSPECTIONS CONDUCTED ON 11/8/84 + 11/9/84
Violation No is modified as follows:
The reasons for this modification are as follows:
Date of Service November 9, 1984 Signature of Authorized Representative
Time of Service or Mailing 5a.m